

Questions and Answers (1)

W912EP-09-B-0020 – Crossroads, Maintenance Dredging

1. What is the bottom elevation of the weir boards and approximately how much material in vertical feet (depth) will need to be removed to get to the bottom board?

Answer: The elevation of the base of the bottom board is approximately 10 feet NGVD29 and given the elevation of dredge material within the site it is assumed there is between 4 and 10 feet of material to be removed to expose all weir boards.

2. Is the USACE providing a staging area and if so, where would that be? If not, can the USACE provide a contact at the County that is in charge of the local Parks?

Answer: Contact the Martin County Parks Department, Administrator, Richard Blankenship (772) 221-1420.

3. Can you provide the name of the contractor, date and the amount of the contracts on the last several projects in this area or other parts of the Cross-Roads?

Answer: This area was last dredged in 1997. Our contract files are destroyed six years after the completion of a project so this information is not available.

4. Per 3.3.2.4 Dike Inspection, what are the required qualifications for the designated dike inspector?

Answer: The dike inspector must be familiar with the different mechanisms of dike failure, listed in section 35 20 23 paragraph 3.3.2.4, and be able to identify them in the field.